
COMMON UPCS FINDINGS

Auxiliary Lock: double key deadbolt



UPCS Inspectable Area: Health & Safety: Emergency/Fire Exits: An additional lock requiring a separate key is required for egress. **Level 3**

Solution: Remove the non-essential keyed deadbolt. Replace with a non-keyed deadbolt if desired (not required).


Auxiliary Lock: above 48" from finished floor



UPCS Inspectable Area: Health & Safety: Emergency/Fire Exits: An auxiliary lock has been installed above 48" from the finished floor. **Level 3**

Solution: Remove the auxiliary lock or relocate the lock to below 48" from the finished floor.


Blocked Egress: bedroom window



UPCS Inspectable Area: Health & Safety: Emergency/Fire Exits: The bedroom egress window has been blocked by furniture. **Level 3**

Solution: Remove the furniture away from the egress window.

Blocked Egress: basement stairs



UPCS Inspectable Area: Health & Safety: Emergency/Fire Exits: The egress stairwell from the basement is blocked by various items. **Level 3**

Solution: Remove all items from the stairwell.


Flammable Materials: stored improperly



UPCS Inspectable Area: Health & Safety: Flammable Materials: Flammable items are being stored near the range. **Level 3**

Solution: Remove all flammable items away from the range.

Hazards: safety hazard



UPCS Inspectable Area: Health & Safety: Hazards: A make-shift antenna is projecting into the stairwell. Level 3

Solution: Remove the antenna from the stairwell.


Hazards: trip hazard



UPCS Inspectable Area: Health & Safety: Hazards: Items are being stored on the stairs presenting a trip hazard. Level 3

Solution: Remove the items from the stairwell.


Hazards: trip hazard



UPCS Inspectable Area: Health & Safety: Hazards: A loose cable is draping over the stairs. **Level 3**

Solution: Remove the cable from the stairwell or secure the cable above the stairwell to eliminate any potential tripping hazard.

Hazards: trip hazard



UPCS Inspectable Area: Health & Safety: Hazards: A loose cable is crossing an egress pathway. **Level 3**

Solution: Remove the cable from the egress pathway. The cable may be secured overhead to eliminate any possible trip hazard.

Electrical Hazards: exposed wires



UPCS Inspectable Area: Units: Electrical: Covers: The cover is missing from a receptacle. Level 3

Solution: Provide a cover or fixture for the receptacle.

Electrical Hazards: damaged receptacles



UPCS Inspectable Area: Units: Electrical: Covers: The receptacle is damaged. Level 3

Solution: Repair/replace the receptacle as necessary.

Electrical Hazards: broken/cracked receptacle covers



UPCS Inspectable Area: Units: Electrical: Covers: The receptacle cover is damaged. Level 3

Solution: Replace the receptacle cover as necessary.

Electrical Hazards: exposed wires



UPCS Inspectable Area: Health & Safety: Electrical Hazards: A panel is open and wires are exposed. **Level 3**

Solution: Provide a UL listed cover for the open panel.


Electrical Panel: blocked by heavy objects



UPCS Inspectable Area: Units: Electrical: Panel: The electrical panel is blocked by a shelf. **Level 3**

Solution: Move the shelf away from the electrical panel to allow 18" of clear area on all sides of the panel.

Electrical Panel: foreign substance



UPCS Inspectable Area: Units: Electrical: Panel: a foreign substance has been applied to the inside of the panel. Level 3

Solution: Remove the foreign substance from the panel. Ensure spaces no larger than 1/8" are present around any breakers. Fill any spaces with a combination of UL listed breakers and spacers.


Fire Protection: missing/expired fire extinguisher



UPCS Inspectable Area: Building Systems: Fire Protection: A fire extinguisher is expired. Level 1 (Level 3 if throughout the building)

Solution: The fire extinguisher must be inspected and tagged.

Smoke detector: missing/does not operate



UPCS Inspectable Area: Units: Smoke Detector: The smoke detector in the basement is missing Level 3

Solution: Install a smoke detector.

Boiler Deficiency: extension pipe not to floor



UPCS Inspectable Area: Building Systems: Domestic Water: The extension tube for the T&P valve does not extend within 18" of the floor. **Level 3**

Solution: Install an extension tube to within 18" of the floor.

HVAC: rusted equipment



UPCS Inspectable Area: Units: HVAC: A radiator cover is rusted. Level 1

Solution: Remove rust from radiator cover or replace as necessary

Flooring: stained/worn carpet



UPCS Inspectable Area: Units: Floors: The carpet is torn and stained. Level 1 (Level 2 or 3 for larger areas)

Solution: Repair and clean or replace carpet as necessary.

Flooring: broken/missing tiles



UPCS Inspectable Area: Units: Floors: Tiles are missing and/or broken. Level 1 (Level 2 or 3 for larger areas)

Solution: Repair or replace floor tiles as necessary.

Ceiling: stained ceiling tiles



UPCS Inspectable Area: Units: Celing: Ceiling tiles are stained, bulging and sagging. Level 3 (Level 1 or 2 for smaller stains that do not damage the ceiling)

Solution: Replace ceiling tiles.

Building Exterior: degraded roof



UPCS Inspectable Area: Building Exterior: Roofs: A portion of the roof is degraded. Level 1 (Level 2 or 3 for larger areas or more severe damage)

Solution: Replace roof shingles as necessary.

Market Appeal: graffiti



UPCS Inspectable Area: Site: Market Appeal: Graffiti is in one place. Level 1 (Level 2 or 3 for more widespread graffiti)

Solution: Remove graffiti as necessary

Site: Erosion



UPCS Inspectable Area: Site: Grounds: A large area of the site is eroded and has caused a degraded surface. Level 2

Solution: Reseed the site as necessary

Pavement: Cracked/heaving



UPCS Inspectable Area: Site: Parking Lots/Driveways/ Roads: A large area of pavement has large cracks, heaving, potholes and settling. Level 2 (Level 3 for more widespread, Level 1 for less)

Solution: Repave the parking lot as necessary.

Walkway: trip hazard



UPCS Inspectable Area: Health & Safety: The walkway has shifted and presents a tripping hazard. Level 3

Solution: Regrade the walkway to eliminate the tripping hazard.

Grounds: vegetation contacting building



UPCS Inspectable Area: Site: Grounds: A tree is contacting the roof of the building. Level 2 (Level 3 for more extensive contact/damage).

Solution: Trim the tree back from the building.